



Fluxa A - Ausleger 8 271 3.1
Flächenstrahler für Wand- 8 273 3.1
und Mastbefestigung

Schutzart IP 65

Schutzklasse I



**MONTAGE
ANLEITUNG**
**MOUNTING
INSTRUCTIONS**



WILLY MEYER & SOHN GMBH & CO.KG
LICHTTECHNISCHE SPEZIALFABRIK
 Stemmessiepener Weg 5 • D-58675 Hemer

Flächenstrahler für Halogen-Metaldampflampen HIT-DE, HIT-DE-CE, Natriumdampf-Hochdrucklampen HST-DE 70 / 150 Watt, Fassung Rx7s.

MONTAGEHINWEISE

Anschluß der Leuchte nach VDE 0100.
 Flächenstrahler für ungeschützte Anlagen.
 Leuchte ist geeignet für Montage auf normal entflammabaren Baustoffen.
 **Achtung Hochspannung !**
 Vor dem Öffnen der Leuchte oder Lampenwechsel Netzspannung trennen.

Montage am Mastaufsatz

Auf ausreichende Dimensionierung des Mastes achten, ggf. Rücksprache mit dem Masthersteller nehmen.
 Rahmen-Befestigungsschrauben lösen.
 Rahmen mit Glas anheben und vom Gehäuse schwenken.
 Je nach Masthöhe ausreichend lange Netzanschußleitung durch die Kabelverschraubung führen, Leitung 9 cm abmanteln und beiliegende Silikonschlüsse über die Einzeladern ziehen.
ACHTUNG ! Mantelleitung darf maximal 2 cm in das Leuchtengehäuse ragen.
 Elektrischen Anschluß vornehmen.
 Kabelverschraubung festdrehen.
 Lampe einsetzen, dabei auf richtige Bestückung laut Typenschild achten.
 Bei HS-Lampen nur solche mit  - Kennzeichnung einsetzen.
 Rahmen mit Glas auf Gehäuse schwenken und dicht verschrauben.
 Leuchte an die Schrauben M10 x 40 am Mastaufsatz einhängen und mit einem Drehmoment von 44 Nm anziehen.
 Die Gewindestecksel im Mastaufsatz sind selbstsichernd.
 Das Anschlußkabel durch die Bohrung im Mastaufsatz schieben und am Kabel-übergangskasten im Mast anschließen.


Montage an der Wandplatte

Auf ausreichende Befestigung der Wandplatte auf dem Montagegrund achten ! Leuchte an die entsprechenden Schrauben M10 x 40 einhängen und die Schrauben mit einem Drehmoment von 44 Nm anziehen. Die Gewindestecksel in der Wandplatte sind selbstsichernd. Zuleitung durch die Kabelverschraubung in die Leuchte einführen und wie zuvor beschrieben anschließen.

Montage auf anderen Oberflächen

Auf ausreichende Festigkeit des Montagegrundes achten. Zur Befestigung der Leuchte mind. zwei rostfreie Schrauben M10 der Festigkeit 70 verwenden und für einen ausreichenden Lockerungsschutz sorgen. Elektrischen Anschluß wie zuvor beschrieben vornehmen.

Das Glas ist ein Einscheiben-Sicherheits-Hartglas.




Die Leuchte darf nur mit ihren vollständigen Schutzbekleidungen betrieben werden.

Leuchte	Gewicht	Windangriffsfläche
8 271 3.1	9,0 kg	0,11 m ²
8 273 3.1	9,5 kg	0,11 m ²



In Strahlrichtung den Mindestabstand zu angestrahlten Flächen einhalten !



8 271 3.1



8 273 3.1





Fluxa A - with arm
Area floodlight for wall-
or pole mounting

8 271 3.1
8 273 3.1

Protection IP 65
Safety Class I



MONTAGE
ANLEITUNG
MOUNTING
INSTRUCTIONS



WILLY MEYER & SOHN GMBH & CO.KG
LICHTTECHNISCHE SPEZIALFABRIK
Stemmessiepener Weg 5 • D-58675 Hemer

Area floodlight for metal halide lamps
HIT-DE, HIT-DE-CE,
high pressure sodium lamps HST-DE
70 / 150 Watts, lampholder Rx7s.

MOUNTING INSTRUCTIONS

Connect the light fitting in compliance with prevailing regulations in your country.
Luminaire for non-protected outdoor installation.

Light fitting is suitable for installation on normal inflammable building materials.

Attention ! High Voltage !

Disconnect power supply before opening light fitting or changing lamp.

Mounting on pole top fitter

Ensure that the correct size of pole is chosen; if necessary consult the pole manufacturer.

Loosen screws in front frame. Lift frame and glass and swing away from casing.

Depending on height of pole, take a sufficiently long piece of cable and insert it through the cable gland.

Strip the sheathing off the last 9 cm of cable and slide the enclosed silicone sleeves over the individual wires.

ATTENTION ! Do not insert more than 2 cm of sheathed cable into luminaire housing.

Make the electrical connection.

Screw cable gland tight. Insert lamp, taking care to use the correct lamp as mentioned on the rating plate. If a high pressure sodium lamp is to be used, make sure that only lamps bearing the sign are used.

Swing front frame and glass back onto casing and screw down evenly.

Hang the luminaire onto the M10 x 40 screws on the pole top fitter and tighten with 44 Nm torque. The threaded inserts in the pole top fitter are self locking.

Push cable through hole in pole and connect to connection box in base of pole.

Mounting on the Wall Plate


Make sure that the wall plate is sufficiently securely fixed to the installation surface.

Hang the luminaire onto the M10 x 40 screws and tighten them with a torque of 44 Nm. The threaded inserts in the wall plate are self locking. Insert the cable through the cable gland into the luminaire and then proceed with the electrical connection as mentioned above.

Mounting on other surfaces

Make sure that the installation surface is sufficiently stable and strong. To attach the luminaire, use at least 2 stainless steel M10 screws of hardness 70. Take adequate precautions to prevent the screws from loosening. Make electrical connection as mentioned above.


The glass is toughened safety glass.




The light fitting may be operated only if all protective covers are in place.

Type	Weight	Projected area
8 271 3.1	9,0 kg	0,11 m ²
8 273 3.1	9,5 kg	0,11 m ²

Ensure that the minimum spacing between luminaire and illuminated surface is observed.



8 271 3.1



8 273 3.1

